

C.L. "BUTCH" OTTER - Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888. E-mail: fsb@idhw.state.id.us

March 16, 2007

Bart Larsen, Administrator Mount Vernon - Potomac Investments, LLC 3620 Potomac Way Idaho Falls, ID 83404

License #: RC-788

Dear Mr. Larsen:

On February 27, 2007, a life safety code survey was conducted at Mount Vernon - Potomac Investments, Llc. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Taylor Barkley, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

TAYLOR BARKLEY

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

TB/sc

c:

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program



C.L. "BUTCH" OTTER, Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

March 6, 2007

Bart Larsen, Administrator Mount Vernon - Potomac Investments, LLC 3620 Potomac Way Idaho Falls, ID 83404

Dear Mr. Larsen:

On February 27, 2007, a life safety code survey was conducted at Mount Vernon - Potomac Investments, LLC. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by March 29, 2007.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION COMPLETED IDENTIFICATION NUMBER: A. BUILDING 01 - ENTIRE BUILDING B. WING 02/27/2007 13R788

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

' TNUOI	VERNON - POTOMAC INVESTMENTS,		TOMAC WAY ALLS, ID 8340	4	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY REGULATORY OR LSC IDENTIFYING INFORM	FULL .	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
R 000	Initial Comments The facility was found to be in substantic compliance with the fire and life safety requirements of the Rules for Residenti Assisted Living Facilities in Idaho. No odeficiencies were cited during the standfire/life safety survey conducted on Feb 2007. The surveyor conducting the survey was Taylor Barkley Health Facility Surveyor Facility Fire safety & Construction	al or ore lard ruary 27,	R 000		

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

6899 If continuation sheet 1 of 1 STATE FORM E54C21



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

Facility Name	Physical Address	Phone Number
Mount Vernon	3620 Patomac WAY	(208) 528-0467
Administrator	City	ZIP Códe
Bart Larsen	Idaho Falls Id	83404
Survey Team Leader	Survey Type	Survey Date
Taylor BANKICY		2-27-7

Survey	Team Leader		Survey Type	Survey Date		
TA	aylor B	arkley		9-5	7-7	
NON	-CORE ISSU	ES				,
ITEM #	RULE # 16.03.22		DESCRIPTION		DATE RESOLVED	BFS USE
1	410.02	The Facility did not co	suchet the one drill pershift	per		30500
		Quarter requirement	hey held tive drills during t	, Λ Έ		
		previous twelve mo			7	
9.	405.01	Resident room # 2 hi	BE AN extension cord in use.			
3.	405.01	Resident room # 10 h	AS AN extension rord in use.			12 (18/05)
<u></u>	405.01	Resident room # 7 h	AS A multiple electrical Adapter	1/2 USC.		
			'		1	
5	405.05	The mechanical roo	m has multiple penetrations	of		
		the ceiling from con	Duit And piping		A	
	/		' '		7-11-11-11-11-11-11-11-11-11-11-11-11-11	
6	415,05	The fallity has not	had AN ANNUAL Sprinkler system	n Impection	~.	
		,		,	Veniment of the second of the	1818
7.	415.02	The facility has not h	ad an Annual inspection on the fu	ol-Gired		
		heating devices,	<u>'</u>			
				w		media se
Response Required Date		Signature of Facility Representative			Date Signed	
3.3	3.7-7	Sar/an-			3-27-07	L.
		Ministran contract of the second contract of			وسد وسدوس وسر	m 1

2-2207 (

BFS-686 March 2006

9/04 🖟